

APPLICATION TECHNIQUES – SNOW PRINTS

NOTE: When casting SNOW marks it is important to cool the cartridge down to the outside temperature before application to avoid melting the mark. At low and freezing temperatures the compound will take longer to cure.

